



Technical Service Bulletin

Technical Service Bulletin: tsb102541

Released Date: 01-Nov-2007

Revision, Clean and Inspect for Reuse Step, Connecting Rod Procedure

Revision, Clean and Inspect for Reuse Step, Connecting Rod Procedure

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

This Service/Parts Topic adds information about supporting the connecting rod at the large bearing end to avoid I-beam damage in Procedure 001-014 (Connecting Rod) in Signature, ISX, and QSX15 Service Manual Bulletin 3666239.

Related Procedures

10-001-014
(/qs3/pubsys2/xml/en/procedures/10/10-001-014.html)

Connecting Rod
(/qs3/pubsys2/xml/en/procedures/10/10-001-014.html)

Last Modified: 01-Nov-2007