



Technical Service Bulletin

Technical Service Bulletin: tsb102563

Released Date: 10-Dec-2007

Revision, Multiple Steps, (Crankshaft Seal, Front) and (Gear Cover, Lower) Procedures

Revision, Multiple Steps, (Crankshaft Seal, Front) and (Gear Cover, Lower) Procedures

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

This Service/Parts Topic revises Procedure 001-023 (Crankshaft Seal, Front) and Procedure 001-080 (Gear Cover, Lower). Both procedures were updated to clarify the replacement of the lower gear covers with a beveled half groove or a full o-ring groove under the crankshaft seal flange.

The full o-ring groove covers, contain an o-ring in the lower gear cover groove and were only used prior to June 5, 1999. The lower gear cover **must** be replaced if installing a new seal.

The beveled half groove covers do **not** contain an o-ring and **only** require replacement if damaged.

Related Procedures

10-001-023 (/qs3/pubsys2/xml/en/procedures/10/10-001-023.html)	Crankshaft Seal, Front (/qs3/pubsys2/xml/en/procedures/10/10-001-023.html)
10-001-080 (/qs3/pubsys2/xml/en/procedures/10/10-001-080.html)	Gear Cover, Lower (/qs3/pubsys2/xml/en/procedures/10/10-001-080.html)

Last Modified: 10-Dec-2007