



Technical Service Bulletin

Technical Service Bulletin: tsb102613	Released Date: 20-Dec-2007
Revision, Multiple Steps, Fault Code 115, 121, and 433	

Revision, Multiple Steps, Fault Code 115, 121, and 433

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

This Service/Parts Topic revises multiple steps in the following fault codes:

Guided Step 2D to replace the ECM for active fault code 115 if no other faults are identified.

Guided Step 2D to replace the ECM for active fault code 121 if no other faults are identified.

Guided Step 4E to replace the ECM for active fault code 343 if no other faults are identified.

Camshaft Engine Position Sensor Circuit Crankshaft Engine Position Sensor Circuit Electronic Control Module (ECM)

Last Modified: 20-Dec-2007
