



Technical Service Bulletin

Technical Service Bulletin: tsb102706	Released Date: 04-Mar-2008
Revision, Troubleshooting Tree t021, Coolant Loss - Internal	

Revision, Troubleshooting Tree t021, Coolant Loss - Internal

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

This Service/Parts Topic introduces an additional step in the Coolant Loss - Internal troubleshooting symptom tree for the Signature™, ISX, and QSX15 Service Manual, Bulletin 3666239.

An incorrect or malfunctioning radiator cap can have an effect on the cooling system and cooling system components. The second step in the Coolant Loss - Internal symptom tree identifies a cause and correction relating to the radiator cap.

Coolant Loss - Internal

Last Modified: 04-Mar-2008
