



Technical Service Bulletin

Technical Service Bulletin: tsb103053

Released Date: 01-Oct-2008

(Flywheel Housing, REPTO) Procedure, Install Section Revision

(Flywheel Housing, REPTO) Procedure, Install Section Revision

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

This Service/Parts Topic revises Procedure 016-007 (Flywheel Housing, REPTO) to include a step to check for backlash between the Hydrive housing gear and the idler gear. It has been determined that a small amount of backlash **must** be present for correct operation. A no backlash condition can cause premature component failure.

Related Procedures

10-016-007-tr
(/qs3/pubsys2/xml/en/procedures/10/10-016-007-tr.html)

Flywheel Housing, REPTO
(/qs3/pubsys2/xml/en/procedures/10/10-016-007-tr.html)

Last Modified: 01-Oct-2008