



Technical Service Bulletin

Technical Service Bulletin: tsb103140

Released Date: 21-Oct-2008

Camshaft Bushings Procedure, Multiple Section Revisions

Camshaft Bushings Procedure, Multiple Section Revisions

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

This Service/Parts topic changes specifications in multiple sections of Procedure 001-010 (Camshaft Bushings) in Section 1 of the K19 Service Manual, Bulletin 4021499. The camshaft bushing removal and installation tool part numbers were revised.

Related Procedures

18-001-010

(/qs3/pubsys2/xml/en/procedures/18/18-001-010.html)

Camshaft Bushings

(/qs3/pubsys2/xml/en/procedures/18/18-001-010.html)

Last Modified: 21-Oct-2008