



Technical Service Bulletin

Technical Service Bulletin: tsb103267

Released Date: 17-Dec-2008

Rocker Lever Assembly Procedure, Torque Revision

Rocker Lever Assembly Procedure, Torque Revision

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

This Service/Parts Topic documents a revision to the torque value of the rocker lever assembly mounting capscrews in the Install section of Procedure 003-009 (Rocker Lever Assembly).

Related Procedures

18-003-009-tr
(/qs3/pubsys2/xml/en/procedures/18/18-003-009-tr.html)

Rocker Lever Assembly
(/qs3/pubsys2/xml/en/procedures/18/18-003-009-tr.html)

Last Modified: 17-Dec-2008