



Technical Service Bulletin

Technical Service Bulletin: tsb103283	Released Date: 16-Jan-2009
Engine Performance Troubleshooting Tree, Guided Step 5B Revision	

Engine Performance Troubleshooting Tree, Guided Step 5B Revision

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

This Service/Parts Topic revises Guided Step 5B in the Engine Performance Troubleshooting Tree, adding a note about repeating the test step if more than one injector is malfunctioning.

Engine Performance Troubleshooting Tree

Last Modified: 16-Jan-2009
