



Technical Service Bulletin

Technical Service Bulletin: tsb103303

Released Date: 23-Jan-2009

Piston and Connecting Rod Assembly Procedure (Section Addition), and Connecting Rod Procedure (Section Revision).

Piston and Connecting Rod Assembly Procedure (Section Addition), and Connecting Rod Procedure (Section Revision).

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

This Service/Parts Topics adds a Clean and Inspect for Reuse section in Procedure 001-054 (Piston and Connecting Rod Assembly) and removes a torque table in the Bend and Twist Inspect section in Procedure 001-014 (Connecting Rod).

Related Procedures

18-001-014 (/qs3/pubsys2/xml/en/procedures/18/18-001-014.html)	Connecting Rod (/qs3/pubsys2/xml/en/procedures/18/18-001-014.html)
18-001-054 (/qs3/pubsys2/xml/en/procedures/18/18-001-054.html)	Piston and Connecting Rod Assembly (/qs3/pubsys2/xml/en/procedures/18/18-001-054.html)

Last Modified: 23-Jan-2009