



Technical Service Bulletin

Technical Service Bulletin: tsb103341

Released Date: 06-Feb-2009

Maintenance Schedule, Radiator Pressure Cap Check Addition

Maintenance Schedule, Radiator Pressure Cap Check Addition

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

This Service/Parts Topic revises Procedure 102-002 (Maintenance Schedule) in Section 2 of the ISX Owners Manual, Bulletin 4960314, to add the Radiator Pressure Cap maintenance check. The manual is being revised to make sure the radiator pressure cap is functioning correctly. The system **must** maintain pressure to make sure of proper engine performance.

Related Procedures

10-102-002-owner-auto
(/qs3/pubsys2/xml/en/procedures/10/10-102-002-owner-auto.html)

Maintenance Schedule
(/qs3/pubsys2/xml/en/procedures/10/10-102-002-owner-auto.html)

Last Modified: 06-Feb-2009