



# Technical Service Bulletin

Technical Service Bulletin: tsb103429

Released Date: 25-Mar-2009

(Bracket, Accessory) Procedure, Install Section Revision

## (Bracket, Accessory) Procedure, Install Section Revision

### Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

### Contents

This Service/Parts Topic revises the Install Section of Procedure 001-082 (Bracket Accessory) in Section 1 of the Signature™, ISX, and QSX15 Service Manual, Bulletin 3666239. An instruction to apply a heavy moly grease to the area of contact between the brace and the cylinder head has been added.

### Related Procedures

10-001-082  
(/qs3/pubsys2/xml/en/procedures/10/10-001-082.html)

Bracket, Accessory  
(/qs3/pubsys2/xml/en/procedures/10/10-001-082.html)

Last Modified: 25-Mar-2009