



Technical Service Bulletin

Technical Service Bulletin: tsb103441	Released Date: 31-Mar-2009
Fault Code 255, Major Revision	

Fault Code 255, Major Revision

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

This Service/Parts Topic revises all of the troubleshooting steps for Fault Code 255 (Fuel Shutoff Valve Solenoid Supply Circuit) in Troubleshooting and Repair Manual, Electronic Control System, Signature™, ISX, and QSX15, Bulletin 3666259.

Engine Fuel Shutoff Valve Drive Circuit - Voltage Above Normal or Shorted to High Source

Last Modified: 31-Mar-2009
