



Technical Service Bulletin

Technical Service Bulletin: tsb103446	Released Date: 15-Apr-2009
Fault Code 449, Component Location Section Revision	

Fault Code 449, Component Location Section Revision

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

This Service/Parts Topic updates the Hydraulic Fuel System Component location section of Fault Code 449. The changes improve component identification.

High Fuel Pressure

Last Modified: 15-Apr-2009
