



Technical Service Bulletin

Technical Service Bulletin: tsb103592	Released Date: 09-Sep-2009
Symptom Trees t021 (Coolant Loss) - Internal) and t025 (Coolant in the Lubricating Oil), Service Practice Clarifications	

Symptom Trees t021 (Coolant Loss) - Internal) and t025 (Coolant in the Lubricating Oil), Service Practice Clarifications

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

This Service/Parts Topic revises Troubleshooting Symptom Tree t021 (Coolant Loss - Internal) and t025 (Coolant in the Lubricating Oil) to clarify the action to be taken when the injectors are removed for inspection.

Coolant Loss - Internal Coolant in the Lubricating Oil

Last Modified: 09-Sep-2009
