



# Technical Service Bulletin

---

|                                                 |                            |
|-------------------------------------------------|----------------------------|
| Technical Service Bulletin: tsb103635           | Released Date: 19-Apr-2010 |
| Fault Code 393, Guided Step 1A and 1B Revisions |                            |

## Fault Code 393, Guided Step 1A and 1B Revisions

### Warranty Statement

---

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

### Contents

---

This Service/Parts Topic revises Fault Code 393, Step 1A and 1B in the Signature™, ISX, and QSM15 Electronic Control System Troubleshooting and Repair Manual, Bulletin 3666259.

Engine Brake Supply Circuit

---

**Last Modified: 19-Apr-2010**

---