



Technical Service Bulletin

Technical Service Bulletin: tsb103878

Released Date: 16-Sep-2009

Injector Procedure, Disassemble and Assemble Section Revisions

Injector Procedure, Disassemble and Assemble Section Revisions

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

This Service/Parts Topic announces changes to the Disassemble and Assemble Sections in Procedure 006-026 (Injector) in the Signature™, ISX, and QSX15 Service Manual, Bulletin 3666239. The procedure presently **only** includes instructions for replacing the upper injector seal on injectors with roll pin retained load rings. The revised procedure adds the information to replace the upper injector seals on injectors with clip retained load rings.

Related Procedures

10-006-026-tr
(/qs3/pubsys2/xml/en/procedures/10/10-006-026-tr.html)

Injector
(/qs3/pubsys2/xml/en/procedures/10/10-006-026-tr.html)

Last Modified: 16-Sep-2009