



Technical Service Bulletin

Technical Service Bulletin: tsb103916

Released Date: 17-Aug-2009

Lubricating Oil Pump Procedure, Install Section Revision

Lubricating Oil Pump Procedure, Install Section Revision

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

This Service/Parts Topic revises Procedure 007-031 (Lubricating Oil Pump) to to clarify the correct factory specification for measuring the oil pump gear backlash.

Related Procedures

10-007-031-tr
(/qs3/pubsys2/xml/en/procedures/10/10-007-031-tr.html)

Lubricating Oil Pump
(/qs3/pubsys2/xml/en/procedures/10/10-007-031-tr.html)

Last Modified: 17-Aug-2009