



Technical Service Bulletin

Technical Service Bulletin: TSB140059

Released Date: 09-May-2014

Brushless Alternator Option For Harsh Environmental Conditions

Brushless Alternator Option For Harsh Environmental Conditions

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

This document is to inform the field if a machine is experiencing charging issues with a 24SI alternator, in conditions with excessive dust and debris, the 33SI alternator is recommended as a replacement. The 33SI is a brushless alternator and serves as a better alternative.

Engine Family	Standard Duty Alternator Option/Part Number 24SI	Harsh Environment Alternator Option/Part Number 33SI	Description
QSM11 CM570	EE2072/2874863	EE2046/4000590	Alternator
QSX15 CM570	EE1269/2874863	EE1240/4000590	Alternator

Document History

Date	Details
2014-5-8	Module Created

Last Modified: 09-May-2014