



Technical Service Bulletin

Technical Service Bulletin: TSB140163

Released Date: 17-Dec-2014

ISX15 and QSX15 External Coolant or Oil Leak from Lubricating Oil Cooler

ISX15 and QSX15 External Coolant or Oil Leak from Lubricating Oil Cooler

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

Product Affected

ISX15 and QSX15 engines.

Description of Change

Lubricating oil cooler gasket has a thicker bead.

Reason for Change

External coolant or oil leak from lubricating oil cooler. The thicker lubricating oil cooler gasket bead improves sealing capability.

Service Part Available

Service parts are available. See Table 1 for part numbers.

Table 1, Part Numbers

Part Description	Obsolete Part Number	New Part Number
Gasket	3104232	3689755

Part Structure

The part is backward compatible and transparent to assembly.

The existing part number has been obsoleted and superseded by the new part number.

Part Disposition

Use existing part number inventory before using the new part number.

Production Status

Implemented for production. See Table 2.

Table 2, Plant Information			
New Part Number	ESN First	Build Date	Plant
3689755	Not Available	20 October 2014	Jamestown Engine Plant
Engine build date can be found on the engine dataplate.			
The following plants may also be affected, however ESN first and build date information is not available. Cummins S.A. (Mexico) Publications Affected None.			

Document History

Date	Details
2014-11-19	Module Created