



Technical Service Bulletin: TSB170009

Released Date: 19-Jan-2017

Coolant in Lubricating Oil: Water Pump Weep Hole Plug Removal

Coolant in Lubricating Oil: Water Pump Weep Hole Plug Removal

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

Product Affected

Engine:

- QSK23 CM500
- QSK23 CM2250 K109
- QSK23 PG CM850

Engine Serial Number (ESN) Range:

- 85000000 and above

Issue

Symptom:

- Coolant in lubricating oil.

Root Cause:

- A rubber plug is installed on water pump weep hole, preventing coolant from exiting water pump weep hole and entering into lubricating oil. Water pump weep hole plug is installed at factory and **must** be removed before operating engine.

Verification

- Inspect water pump weep hole for plug. See Figure 1 below.



Figure 1, Water Pump Weep Hole Plug.

Resolution

- Remove plug from water pump weep hole.

Document History

Date	Details
2017-1-17	Module Created

Last Modified: 19-Jan-2017
