



Technical Service Bulletin

Technical Service Bulletin: TSB170094

Released Date: 19-Sep-2017

New Fuel Supply Line

New Fuel Supply Line

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

Product Affected

- ISM (All Versions)
- ISMe (All Versions)
- M11 (All Versions)
- QSM11 (All Versions)

Description of Change

- New fuel supply line is available for production and service.
- Existing fuel supply line material is rigid metal. New fuel supply line material is steel braided flexible polytetrafluoroethylene (PTFE).

Reason for Change

Existing fuel supply line can crack.

Service Instructions

Hand tighten both ends of fuel supply line and support fuel supply line with hand while tightening to avoid kinking of fuel supply line. See corresponding Service Manual. Reference Procedure 006-024 in Section 6.

Service Parts Availability

Service parts are available. See Table 1 for part numbers.

Table 1, Service Parts

Part Description	Existing Part Number	Obsolete	Superseded	New Part Number
Fuel Supply Line	3102752	Yes	Yes	3694045

Part Inventory Action

Existing part numbers in stock are **not** to be used. Existing part numbers in stock are to be returned for reimbursement. See Parts Alert MDC-11-17 for details.

Publications Affected

Table 2, Publications Affected				
Manual Type	Engine	Procedure Title	Procedure	Section
Troubleshooting and Repair	M11	Fuel Supply Lines	006-024	6
Service	ISM, ISMe, and QSM11			

Document History

Date	Details
2017-8-29	Module Created