



Technical Service Bulletin

Technical Service Bulletin: TSB200242

Released Date: 06-Jan-2021

New Fuel Pressure Sensor

New Fuel Pressure Sensor

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

Product Affected

- K19 (STC versions **only**)

Description of Change

A new fuel pressure sensor is available.

Reason for Change

Existing fuel pressure sensor can leak. If existing fuel pressure sensor malfunctions, use new fuel pressure sensor part number. See Table 1 below for part number information.

Service Parts Availability

Service parts are available. See Table 1 for part numbers.

Table 1, Service Parts

Part Description	Existing Part Number	Obsolete	Superseded	New Part Number
Fuel Pressure Sensor	5462262	No	No	3408606

Document History

Date	Details
2020-12-8	Module Created

