



Technical Service Bulletin: TSB240230

Released Date: 08-Aug-2025

Changes to Engine Control Module (ECM) Calibration Downloads with Cummins®
Electronic Service Tool

Changes to Engine Control Module (ECM) Calibration Downloads with Cummins® Electronic Service Tool

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

Product Affected

- Engines with managed engine control module (ECM) calibration transfers will be identified by the service tool

Issue Summary

- Beginning with Guidanz Diagnostic Tool Kit (DTK) mobile version 7.3/Windows version 3.3 and INSITE™ electronic service tool version 9.2 which is scheduled for release in August 2025, the Service Calibration Management (SCM) will begin to manage calibration installs to the engine control module (ECM). The SCM is a process the Cummins® Electronic Service Tool uses to determine the correct calibration and provides the authorization for the calibration install to the ECM. Reference Service Bulletin, Engine Control Module (ECM) Calibration Download with Cummins® Electronic Service Tools, Bulletin 6643906.
- This update is being implemented to ensure Cummins® products remain compliant for their entire life cycles.
- As a reminder, ECM codes should **never** be changed unless instructed to do so through authorized communications such as a Technical Service Bulletin (TSB) or Campaign/Temporary Repair Practice (TRP). Tool users **must always** follow Cummins® Global Engine and Engine System Anti-Tampering Policy (CCP-0038) as well as the Policy on Tampered Emissions Control Devices (CORP-24-0830-012) and the law everywhere.
- For more information on rating changes reference Technical Service Bulletin, Rating Changes for EPA Model Year 2021 and Newer On Highway Product, TSB200206.

Document History

Date	Details
2024-11-18	Module Created
2025-7-2	Added reference to Bulletin 6643906.

Last Modified: 08-Aug-2025
