



Technical Service Bulletin

Technical Service Bulletin: TSB140141

Released Date: 25-Nov-2014

Exhaust Gas Recirculation (EGR) Cooler Connection Adapter Exhaust Outlet Tube

Exhaust Gas Recirculation (EGR) Cooler Connection Adapter Exhaust Outlet Tube

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.


Contents

This document addresses the ISX12 CM2350 X102 and ISX15 CM2350 X 101 engines equipped with Exhaust Outlet Pipe Assembly, Cummins® Part Number 3689355. The exhaust outlet tube part numbers for this option are: Cummins® Part Numbers 3688486 and 3683940. If a leak of the joint between the exhaust outlet pipe and the exhaust manifold or a leak between the EGR cooler and exhaust outlet pipe occurs, **only** replace the exhaust outlet pipe assembly, Cummins® Part Number 3689355. Do **not** replace the exhaust manifold seals. Use the following procedures for directions on removal and installation of the adapter. Refer to Procedure 011-024 in Section 11 for the ISX12 CM2350 X102 Service Manual, Bulletin 4310646.

(/qs3/pubsys2/xml/en/procedures/174/174-011-024-tr-pbix13.html) Refer to Procedure 011-024 in Section 11 for the ISX15 CM2350 X101 Service Manual, Bulletin 4310641.

(/qs3/pubsys2/xml/en/procedures/173/173-011-024-tr-prix13.html)

Reference Number	Item Number	Quantity	Item Name
1	3683940	2	Seal, Exhaust Manifold
2	3688486	1	Pipe, Exhaust Outlet
Assembly	3689355	1	Assembly, Exhaust Outlet Pipe



Document History

Date	Details
2014-9-30	Module Created

Last Modified: 25-Nov-2014