



Technical Service Bulletin

Technical Service Bulletin: TSB210080

Released Date: 14-Apr-2023

Self-Calibrating Turbocharger Actuator

Self-Calibrating Turbocharger Actuator

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

Product Affected

- X15 CM2350 X114B
- X15 CM2350 X116B
- X15 CM2450 X124B
- X15 CM2450 X134B

Description of Change

- This document announces a new turbocharger actuator that has a self-calibrating capability.
- INSITE™ electronic service tool is **not** required to install/calibrate the new turbocharger actuator.

Reason for Change

A new self-calibrating turbocharger actuator can be installed in place of a non self-calibrating turbocharger actuator. See Table 1.

To facilitate field installation of the turbocharger actuator without the use of INSITE™ electronic service tool.

Service Instructions

Use of the incorrect procedure will result in an electronic service tool status message indicating the procedure was stopped or failed.

Reference the corresponding Service Manual procedure if using a self-calibrating turbocharger actuator part number, identified by the instructions in the turbocharger actuator kit box.

Service Parts Availability

Service kits are available. See Table 1 for part numbers.

Table 1, Service Parts					
Part Description	Non self-calibrating Part Number	Obsolete	Superseded	Self-calibrating Part Number	Engine
Electronic Turbo Actuator Kit	6382093	No	No	5602216	X15 CM2450 X134B
					X15 CM2450 X124B
					X15 CM2350 X116B
	6374772			5602216	X15 CM2350 X114B

Publications Affected

Service Procedure 010-134 has been updated to incorporate the installation instructions for self-calibrating turbocharger actuators. See Table 2 below.

Table 2, Publications Affected					
Manual Type	Engine	Bulletin Number	Procedure Title	Procedure	Section
Service	X15 CM2350 X114B	5411181	Variable Geometry Turbocharger Actuator, Electric	Refer to Procedure 010-134 (/qs3/pubsys2/xml/en/procedures/377/377-010-134.html)	10
	X15 CM2350 X116B	5411186		Refer to Procedure 010-134 (/qs3/pubsys2/xml/en/procedures/453/453-010-134.html)	
	X15 CM2450 X134B	5613373		Refer to Procedure 010-134 (/qs3/pubsys2/xml/en/procedures/643/643-010-134.html)	
	X15 CM2450 X124B	5504583		Refer to Procedure 010-134 (/qs3/pubsys2/xml/en/procedures/564/564-010-134.html)	

Document History

Date	Details
2021-4-9	Module Created
2021-6-9	Corrected part number in Table 1 to 5602216.

Date	Details
2023-4-13	Updated Reason for Change, Service Instructions, and Table 1.

Last Modified: 14-Apr-2023
