



Technical Service Bulletin: TSB220096

Released Date: 12-Jun-2023

Fault Code 5383 Aftertreatment Diesel Particulate Filter (DPF) Ash Load Percent - Maintenance

Fault Code 5383 Aftertreatment Diesel Particulate Filter (DPF) Ash Load Percent - Maintenance

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

Product Affected

- B6.7 CM2350 B121B
- B6.7 CM2450 B155B
- L9 CM2350 L116B
- L9 CM2350 L123B
- L9 CM2450 L126B
- X12 CM2350 X119B
- X12 CM2450 X137B
- ISX15 CM2350 X101
- X15 CM2350 X114B
- X15 CM2350 X116B
- X15 CM2450 X124B
- X15 CM2450 X134B

Issue

- Aftertreatment diesel particulate filters (DPF) fill with ash over time and require service. Ash accumulation is variable and based on many duty cycle factors. To optimize maintenance costs, use of the maintenance lamp as an indicator for DPF maintenance is recommended.
- Fault Code 5383 is the Aftertreatment Diesel Particulate Filter (DPF) maintenance fault code.
- The aftertreatment DPF intervals **must** be referenced before troubleshooting.
- If the DPF has met the published intervals, then the customer is responsible for coverage.
- Inform the customer of coverage before troubleshooting if the customer is responsible for coverage.

Service Instructions

See the corresponding Owners Manual or Operation and Maintenance Manual. Reference Procedure 359-006 in Section 3.

Document History

Date	Details
2022-5-5	Module Created
2022-6-21	Removed ISL9 CM2350 L101.
2022-9-27	Added L9 products to Product Affected list.
2022-9-27	Corrected typo of service model name.
2023-6-12	Corrected typo of service model name.

Last Modified: 12-Jun-2023