



Technical Service Bulletin: TSB220204

Released Date: 12-Dec-2024

Aftertreatment Diesel Exhaust Fluid (DEF) Dosing Unit Circuit Load Test

Aftertreatment Diesel Exhaust Fluid (DEF) Dosing Unit Circuit Load Test

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

Product Affected

- B6.7 CM2350 B121B
- B6.7 CM2450 B155B
- L9 CM2350 L116B
- L9 CM2350 L123B Transit Bus Application
- L9 CM2450 L126B
- QSK19 CM2350 K105
- QSK19 CM2350 K114
- QSK19 CM2450 K155G
- QSK23 CM2350 K127
- QSK50 CM2350 K108
- QSK60 CM2350 K116
- QSK60 CM2350 K117
- QSK60 CM2350 K121
- QSK78 CM2350 K126
- QSK95 CM2350 K113
- QST30 CM2350 T101
- X12 CM2350 X119B
- X12 CM2450 X137B
- X15 CM2350 X114B
- X15 CM2350 X116B
- X15 CM2350 X132C
- X15 CM2450 X124B
- X15 CM2450 X134B
- X15 CM2450 X142B

Issue Summary

Symptom:

- Fault code 1682, 3574, 4456, 4466, 5747, 5755, 5767, 5775, 5813, 5814, 5828, 5829, 5865, 5867, 6486, 8525, 11144, or 11146

Resolution

- Perform troubleshooting as published in the applicable Fault Code Troubleshooting Manual.
- If troubleshooting leads to performing the Aftertreatment DEF Dosing Unit Circuit Load Test, Procedure 011-165 in Section 11, reference video link below.
 - The first link is the English video.
 - The second link is the Spanish version of the same video.
 - The third link is the French version of the same video.
- Record the voltage drop and continue following published troubleshooting.

Note : <https://videos.simpleshow.com/IV7HZcCm83>
(<https://videos.simpleshow.com/IV7HZcCm83>)

Note : <https://videos.simpleshow.com/PBuZn7SsAX>
(<https://videos.simpleshow.com/PBuZn7SsAX>)

Note : <https://videos.simpleshow.com/n9tFuDF6Vg>
(<https://videos.simpleshow.com/n9tFuDF6Vg>)

Document History

Date	Details
2022-10-6	Module Created
2023-4-12	Added link to Spanish video.
2023-5-5	Updated Product Affected and title.
2023-6-8	Updated Product Affected list.
2023-6-26	Added link to French video.
2023-6-26	Added sentence about French video.
2023-9-7	Updated Resolution section to mention Procedure 011-165.
2024-12-12	Added X15 CM2450 X142B to Product Affected list.