

# Manual Change History ( 5411480) C Command Connect and Connect Premier Marine Panel Systems PS102, PS103 and PS108 Master Repair Manual

---

|                         |                                                                                                   |
|-------------------------|---------------------------------------------------------------------------------------------------|
| <b>Date</b>             | 15-Jun-2017                                                                                       |
| <b>Section</b>          | Back                                                                                              |
| <b>Procedure Number</b> | 5411480-history<br>(/qs3/pubsys2/xml/en/manual/5411480/5411480-history.html)                      |
| <b>Procedure Title</b>  | Manual Change History                                                                             |
| <b>Update Reason</b>    | New manual for C Command Connect and Connect Premier Marine Panel Systems PS102 released for use. |

|                         |                                                                      |
|-------------------------|----------------------------------------------------------------------|
| <b>Date</b>             | 09-Aug-2019                                                          |
| <b>Section</b>          | Section E - Product and System Identification                        |
| <b>Procedure Number</b> | 513-208-002<br>(/qs3/pubsys2/xml/en/procedures/513/513-208-002.html) |
| <b>Procedure Title</b>  | Component Diagrams                                                   |
| <b>Update Reason</b>    | Added conditional information to include the P103 engine.            |

|                         |                                                                      |
|-------------------------|----------------------------------------------------------------------|
| <b>Date</b>             | 22-Aug-2019                                                          |
| <b>Section</b>          | Section E - Product and System Identification                        |
| <b>Procedure Number</b> | 513-344-003<br>(/qs3/pubsys2/xml/en/procedures/513/513-344-003.html) |
| <b>Procedure Title</b>  | Cummins® Product Technology                                          |
| <b>Update Reason</b>    | Added conditional information to include the P103 engine.            |

|                         |                                                                      |
|-------------------------|----------------------------------------------------------------------|
| <b>Date</b>             | 23-Aug-2019                                                          |
| <b>Section</b>          | Section L - Service Literature                                       |
| <b>Procedure Number</b> | 513-205-001<br>(/qs3/pubsys2/xml/en/procedures/513/513-205-001.html) |
| <b>Procedure Title</b>  | Additional Service Literature                                        |
| <b>Update Reason</b>    | Added conditional information to include the P103 engine.            |

|                         |                                                                              |
|-------------------------|------------------------------------------------------------------------------|
| <b>Date</b>             | 25-Sep-2019                                                                  |
| <b>Section</b>          | Section 15 - Instruments and Controls - Group 15                             |
| <b>Procedure Number</b> | 513-015-091<br>(/qs3/pubsys2/xml/en/procedures/513/513-015-091.html)         |
| <b>Procedure Title</b>  | Transmission Gear Oil Pressure and Temperature Sensor Adapter Wiring Harness |
| <b>Update Reason</b>    | Added PS103 information.                                                     |

|                         |                                                                      |
|-------------------------|----------------------------------------------------------------------|
| <b>Date</b>             | 25-Sep-2019                                                          |
| <b>Section</b>          | Section 15 - Instruments and Controls - Group 15                     |
| <b>Procedure Number</b> | 513-015-109<br>(/qs3/pubsys2/xml/en/procedures/513/513-015-109.html) |
| <b>Procedure Title</b>  | Start/Stop Switch                                                    |
| <b>Update Reason</b>    | Added PS103 information.                                             |

|                         |                                                                      |
|-------------------------|----------------------------------------------------------------------|
| <b>Date</b>             | 25-Sep-2019                                                          |
| <b>Section</b>          | Section 15 - Instruments and Controls - Group 15                     |
| <b>Procedure Number</b> | 513-015-999<br>(/qs3/pubsys2/xml/en/procedures/513/513-015-999.html) |
| <b>Procedure Title</b>  | Instruments and Controls - Overview                                  |
| <b>Update Reason</b>    | Added PS103 information.                                             |

|                         |                                                                                                                                          |
|-------------------------|------------------------------------------------------------------------------------------------------------------------------------------|
| <b>Date</b>             | 26-Sep-2019                                                                                                                              |
| <b>Section</b>          | Section 19 - Electronic Controls - Group 19                                                                                              |
| <b>Procedure Number</b> | 513-019-640<br>(/qs3/pubsys2/xml/en/procedures/513/513-019-640.html)                                                                     |
| <b>Procedure Title</b>  | Transmission Gear Oil Temperature Sensor                                                                                                 |
| <b>Update Reason</b>    | Revised to inform that the transmission gear oil temperature sensor may be OEM supplied, therefore the service tools listed may not fit. |

|                         |                                                                                                                                          |
|-------------------------|------------------------------------------------------------------------------------------------------------------------------------------|
| <b>Date</b>             | 26-Sep-2019                                                                                                                              |
| <b>Section</b>          | Section 19 - Electronic Controls - Group 19                                                                                              |
| <b>Procedure Number</b> | 513-019-641<br>(/qs3/pubsys2/xml/en/procedures/513/513-019-641.html)                                                                     |
| <b>Procedure Title</b>  | Transmission Gear Oil Pressure Sensor                                                                                                    |
| <b>Update Reason</b>    | Revised to inform that the transmission gear oil temperature sensor may be OEM supplied, therefore the service tools listed may not fit. |

|                         |                                                                      |
|-------------------------|----------------------------------------------------------------------|
| <b>Date</b>             | 26-Sep-2019                                                          |
| <b>Section</b>          | Section 19 - Electronic Controls - Group 19                          |
| <b>Procedure Number</b> | 513-019-649<br>(/qs3/pubsys2/xml/en/procedures/513/513-019-649.html) |
| <b>Procedure Title</b>  | OEM Supplied Sensors                                                 |
| <b>Update Reason</b>    | Added Exhaust Temperature Sensor to the Sensor Table.                |

|                         |                                                                                                                                          |
|-------------------------|------------------------------------------------------------------------------------------------------------------------------------------|
| <b>Date</b>             | 26-Sep-2019                                                                                                                              |
| <b>Section</b>          | Section 19 - Electronic Controls - Group 19                                                                                              |
| <b>Procedure Number</b> | 513-019-659<br>(/qs3/pubsys2/xml/en/procedures/513/513-019-659.html)                                                                     |
| <b>Procedure Title</b>  | Exhaust Temperature Switch                                                                                                               |
| <b>Update Reason</b>    | Revised to inform that the transmission gear oil temperature sensor may be OEM supplied, therefore the service tools listed may not fit. |

|                         |                                                                                               |
|-------------------------|-----------------------------------------------------------------------------------------------|
| <b>Date</b>             | 26-Sep-2019                                                                                   |
| <b>Section</b>          | Section TT - Troubleshooting Symptoms (New Format)                                            |
| <b>Procedure Number</b> | 513-t02-1004<br>(/qs3/pubsys2/xml/en/procedures/513/513-t02-1004.html)                        |
| <b>Procedure Title</b>  | Un-requested Engine Start                                                                     |
| <b>Update Reason</b>    | Added PS103 information.                                                                      |
| <b>Date</b>             | 26-Sep-2019                                                                                   |
| <b>Section</b>          | Section TT - Troubleshooting Symptoms (New Format)                                            |
| <b>Procedure Number</b> | 513-t02-1018<br>(/qs3/pubsys2/xml/en/procedures/513/513-t02-1018.html)                        |
| <b>Procedure Title</b>  | Engine Will Not Crank at Helm and/or Customer Interface Box                                   |
| <b>Update Reason</b>    | Added main throttle and back up throttle in neutral position.                                 |
| <b>Date</b>             | 27-Sep-2019                                                                                   |
| <b>Section</b>          | Section TT - Troubleshooting Symptoms (New Format)                                            |
| <b>Procedure Number</b> | 513-t02-1021<br>(/qs3/pubsys2/xml/en/procedures/513/513-t02-1021.html)                        |
| <b>Procedure Title</b>  | Display Does Not Dim or Illuminate                                                            |
| <b>Update Reason</b>    | Added stepblock to check the dimmer switch.                                                   |
| <b>Date</b>             | 27-Sep-2019                                                                                   |
| <b>Section</b>          | Section TT - Troubleshooting Symptoms (New Format)                                            |
| <b>Procedure Number</b> | 513-t02-1029<br>(/qs3/pubsys2/xml/en/procedures/513/513-t02-1029.html)                        |
| <b>Procedure Title</b>  | Engine(s) Have No or Only Partial Response to Throttle or Cummins® Inboard Joystick Operation |
| <b>Update Reason</b>    | Added 'Malfunctioning backup throttle' to shoptalk                                            |

|                         |                                                                        |
|-------------------------|------------------------------------------------------------------------|
| <b>Date</b>             | 27-Sep-2019                                                            |
| <b>Section</b>          | Section TT - Troubleshooting Symptoms (New Format)                     |
| <b>Procedure Number</b> | 513-t02-7266<br>(/qs3/pubsys2/xml/en/procedures/513/513-t02-7266.html) |
| <b>Procedure Title</b>  | Rudder Angle - Open Circuit (Short to High) or Loss of Signal          |
| <b>Update Reason</b>    | Added Code 7664 info.                                                  |
| <b>Date</b>             | 30-Sep-2019                                                            |
| <b>Section</b>          | Section TT - Troubleshooting Symptoms (New Format)                     |
| <b>Procedure Number</b> | 513-t02-7267<br>(/qs3/pubsys2/xml/en/procedures/513/513-t02-7267.html) |
| <b>Procedure Title</b>  | Rudder Angle - Short Circuit (Short to Low)                            |
| <b>Update Reason</b>    | Added Code 7664 information.                                           |
| <b>Date</b>             | 14-Oct-2019                                                            |
| <b>Section</b>          | Section 15 - Instruments and Controls - Group 15                       |
| <b>Procedure Number</b> | 513-015-101<br>(/qs3/pubsys2/xml/en/procedures/513/513-015-101.html)   |
| <b>Procedure Title</b>  | Start Switch                                                           |
| <b>Update Reason</b>    | Revised graphics.                                                      |
| <b>Date</b>             | 15-Oct-2019                                                            |
| <b>Section</b>          | Section 1 - Operating Instructions                                     |
| <b>Procedure Number</b> | 513-101-013<br>(/qs3/pubsys2/xml/en/procedures/513/513-101-013.html)   |
| <b>Procedure Title</b>  | General Operating Instructions                                         |
| <b>Update Reason</b>    | Added PS103 information.                                               |

|                         |                                                                        |
|-------------------------|------------------------------------------------------------------------|
| <b>Date</b>             | 15-Oct-2019                                                            |
| <b>Section</b>          | Section 1 - Operating Instructions                                     |
| <b>Procedure Number</b> | 513-101-137<br>(/qs3/pubsys2/xml/en/procedures/513/513-101-137.html)   |
| <b>Procedure Title</b>  | System Indicator Lamps                                                 |
| <b>Update Reason</b>    | Added PS103 information.                                               |
| <b>Date</b>             | 15-Oct-2019                                                            |
| <b>Section</b>          | Section 15 - Instruments and Controls - Group 15                       |
| <b>Procedure Number</b> | 513-015-099<br>(/qs3/pubsys2/xml/en/procedures/513/513-015-099.html)   |
| <b>Procedure Title</b>  | Drive Application Wiring Harness                                       |
| <b>Update Reason</b>    | Added PS103 information.                                               |
| <b>Date</b>             | 15-Oct-2019                                                            |
| <b>Section</b>          | Section 15 - Instruments and Controls - Group 15                       |
| <b>Procedure Number</b> | 513-015-035<br>(/qs3/pubsys2/xml/en/procedures/513/513-015-035.html)   |
| <b>Procedure Title</b>  | Display(s) and Instrumentation                                         |
| <b>Update Reason</b>    | Added PS103 information.                                               |
| <b>Date</b>             | 17-Oct-2019                                                            |
| <b>Section</b>          | Section TT - Troubleshooting Symptoms (New Format)                     |
| <b>Procedure Number</b> | 513-t02-1008<br>(/qs3/pubsys2/xml/en/procedures/513/513-t02-1008.html) |
| <b>Procedure Title</b>  | Un-requested Engine Stop                                               |
| <b>Update Reason</b>    | Updating TT tree for X15 Maine engine added features.                  |

|                         |                                                                        |
|-------------------------|------------------------------------------------------------------------|
| <b>Date</b>             | 17-Oct-2019                                                            |
| <b>Section</b>          | Section TT - Troubleshooting Symptoms (New Format)                     |
| <b>Procedure Number</b> | 513-t02-1030<br>(/qs3/pubsys2/xml/en/procedures/513/513-t02-1030.html) |
| <b>Procedure Title</b>  | Transmission Gear Oil Pressure Sensor Signal Wrong or Missing          |
| <b>Update Reason</b>    | Updating TT tree for X15 Maine engine added features.                  |

|                         |                                                                        |
|-------------------------|------------------------------------------------------------------------|
| <b>Date</b>             | 17-Oct-2019                                                            |
| <b>Section</b>          | Section TT - Troubleshooting Symptoms (New Format)                     |
| <b>Procedure Number</b> | 513-t02-1036<br>(/qs3/pubsys2/xml/en/procedures/513/513-t02-1036.html) |
| <b>Procedure Title</b>  | Engine Cranks But Will Not Start                                       |
| <b>Update Reason</b>    | Updating TT tree for X15 Maine engine added features.                  |

|                         |                                                                                                   |
|-------------------------|---------------------------------------------------------------------------------------------------|
| <b>Date</b>             | 18-Oct-2019                                                                                       |
| <b>Section</b>          | Section 15 - Instruments and Controls - Group 15                                                  |
| <b>Procedure Number</b> | 513-015-044<br>(/qs3/pubsys2/xml/en/procedures/513/513-015-044.html)                              |
| <b>Procedure Title</b>  | Managing Vessel Personalities                                                                     |
| <b>Update Reason</b>    | The Marine program is changing the location where the vessel personality files (VPF) are located. |

|                         |                                                                                                   |
|-------------------------|---------------------------------------------------------------------------------------------------|
| <b>Date</b>             | 25-Oct-2019                                                                                       |
| <b>Section</b>          | Section 15 - Instruments and Controls - Group 15                                                  |
| <b>Procedure Number</b> | 513-015-107<br>(/qs3/pubsys2/xml/en/procedures/513/513-015-107.html)                              |
| <b>Procedure Title</b>  | Display Software                                                                                  |
| <b>Update Reason</b>    | The Marine program is changing the location where the vessel personality files (VPF) are located. |

|                         |                                                                                                   |
|-------------------------|---------------------------------------------------------------------------------------------------|
| <b>Date</b>             | 22-Oct-2019                                                                                       |
| <b>Section</b>          | Section 15 - Instruments and Controls - Group 15                                                  |
| <b>Procedure Number</b> | 513-015-108<br>(/qs3/pubsys2/xml/en/procedures/513/513-015-108.html)                              |
| <b>Procedure Title</b>  | Display Configuration                                                                             |
| <b>Update Reason</b>    | The Marine program is changing the location where the vessel personality files (VPF) are located. |

|                         |                                                                                                   |
|-------------------------|---------------------------------------------------------------------------------------------------|
| <b>Date</b>             | 21-Oct-2019                                                                                       |
| <b>Section</b>          | Section TT - Troubleshooting Symptoms (New Format)                                                |
| <b>Procedure Number</b> | 513-t02-1007<br>(/qs3/pubsys2/xml/en/procedures/513/513-t02-1007.html)                            |
| <b>Procedure Title</b>  | Starter Does Not Disengage                                                                        |
| <b>Update Reason</b>    | The Marine program is changing the location where the vessel personality files (VPF) are located. |

|                         |                                                                                                   |
|-------------------------|---------------------------------------------------------------------------------------------------|
| <b>Date</b>             | 21-Oct-2019                                                                                       |
| <b>Section</b>          | Section TT - Troubleshooting Symptoms (New Format)                                                |
| <b>Procedure Number</b> | 513-t02-1015<br>(/qs3/pubsys2/xml/en/procedures/513/513-t02-1015.html)                            |
| <b>Procedure Title</b>  | Incorrect Fault Indication                                                                        |
| <b>Update Reason</b>    | The Marine program is changing the location where the vessel personality files (VPF) are located. |



|                         |                                                                                                   |
|-------------------------|---------------------------------------------------------------------------------------------------|
| <b>Date</b>             | 21-Oct-2019                                                                                       |
| <b>Section</b>          | Section TT - Troubleshooting Symptoms (New Format)                                                |
| <b>Procedure Number</b> | 513-t02-1016<br>(/qs3/pubsys2/xml/en/procedures/513/513-t02-1016.html)                            |
| <b>Procedure Title</b>  | Fault Acknowledge Not Operational                                                                 |
| <b>Update Reason</b>    | The Marine program is changing the location where the vessel personality files (VPF) are located. |
| <b>Date</b>             | 21-Oct-2019                                                                                       |
| <b>Section</b>          | Section TT - Troubleshooting Symptoms (New Format)                                                |
| <b>Procedure Number</b> | 513-t02-1017<br>(/qs3/pubsys2/xml/en/procedures/513/513-t02-1017.html)                            |
| <b>Procedure Title</b>  | Display Does Not Indicate When Fault Condition is Active                                          |
| <b>Update Reason</b>    | The Marine program is changing the location where the vessel personality files (VPF) are located. |
| <b>Date</b>             | 21-Oct-2019                                                                                       |
| <b>Section</b>          | Section TT - Troubleshooting Symptoms (New Format)                                                |
| <b>Procedure Number</b> | 513-t02-1019<br>(/qs3/pubsys2/xml/en/procedures/513/513-t02-1019.html)                            |
| <b>Procedure Title</b>  | Engine Will Not Stop From the Helm or Customer Interface Box                                      |
| <b>Update Reason</b>    | The Marine program is changing the location where the vessel personality files (VPF) are located. |

|                         |                                                                                                   |
|-------------------------|---------------------------------------------------------------------------------------------------|
| <b>Date</b>             | 22-Oct-2019                                                                                       |
| <b>Section</b>          | Section TT - Troubleshooting Symptoms (New Format)                                                |
| <b>Procedure Number</b> | 513-t02-1023<br>(/qs3/pubsys2/xml/en/procedures/513/513-t02-1023.html)                            |
| <b>Procedure Title</b>  | Customer Interface Box Circuit Breakers Tripped                                                   |
| <b>Update Reason</b>    | The Marine program is changing the location where the vessel personality files (VPF) are located. |

|                         |                                                                                                   |
|-------------------------|---------------------------------------------------------------------------------------------------|
| <b>Date</b>             | 25-Oct-2019                                                                                       |
| <b>Section</b>          | Section TT - Troubleshooting Symptoms (New Format)                                                |
| <b>Procedure Number</b> | 513-t02-1026<br>(/qs3/pubsys2/xml/en/procedures/513/513-t02-1026.html)                            |
| <b>Procedure Title</b>  | Generator Data Does Not Appear On Display                                                         |
| <b>Update Reason</b>    | The Marine program is changing the location where the vessel personality files (VPF) are located. |

|                         |                                                                                                   |
|-------------------------|---------------------------------------------------------------------------------------------------|
| <b>Date</b>             | 25-Oct-2019                                                                                       |
| <b>Section</b>          | Section TT - Troubleshooting Symptoms (New Format)                                                |
| <b>Procedure Number</b> | 513-t02-1027<br>(/qs3/pubsys2/xml/en/procedures/513/513-t02-1027.html)                            |
| <b>Procedure Title</b>  | Display Vessel Personality File Will Not Import and/or Export                                     |
| <b>Update Reason</b>    | The Marine program is changing the location where the vessel personality files (VPF) are located. |

|                         |                                                                                                   |
|-------------------------|---------------------------------------------------------------------------------------------------|
| <b>Date</b>             | 22-Oct-2019                                                                                       |
| <b>Section</b>          | Section TT - Troubleshooting Symptoms (New Format)                                                |
| <b>Procedure Number</b> | 513-t02-1028<br>(/qs3/pubsys2/xml/en/procedures/513/513-t02-1028.html)                            |
| <b>Procedure Title</b>  | Display Software Will Not Install and/or Update                                                   |
| <b>Update Reason</b>    | The Marine program is changing the location where the vessel personality files (VPF) are located. |

|                         |                                                                                                   |
|-------------------------|---------------------------------------------------------------------------------------------------|
| <b>Date</b>             | 25-Oct-2019                                                                                       |
| <b>Section</b>          | Section TT - Troubleshooting Symptoms (New Format)                                                |
| <b>Procedure Number</b> | 513-t02-1031<br>(/qs3/pubsys2/xml/en/procedures/513/513-t02-1031.html)                            |
| <b>Procedure Title</b>  | OEM Installed Vessel Sensor Information Missing or Intermittent on Display                        |
| <b>Update Reason</b>    | The Marine program is changing the location where the vessel personality files (VPF) are located. |

|                         |                                                                                                   |
|-------------------------|---------------------------------------------------------------------------------------------------|
| <b>Date</b>             | 25-Oct-2019                                                                                       |
| <b>Section</b>          | Section TT - Troubleshooting Symptoms (New Format)                                                |
| <b>Procedure Number</b> | 513-t02-1037<br>(/qs3/pubsys2/xml/en/procedures/513/513-t02-1037.html)                            |
| <b>Procedure Title</b>  | Display Data Incorrect                                                                            |
| <b>Update Reason</b>    | The Marine program is changing the location where the vessel personality files (VPF) are located. |

|                         |                                                                                                   |
|-------------------------|---------------------------------------------------------------------------------------------------|
| <b>Date</b>             | 25-Oct-2019                                                                                       |
| <b>Section</b>          | Section TT - Troubleshooting Symptoms (New Format)                                                |
| <b>Procedure Number</b> | 513-t02-1038<br>(/qs3/pubsys2/xml/en/procedures/513/513-t02-1038.html)                            |
| <b>Procedure Title</b>  | Display Data Alternates Between Different Values                                                  |
| <b>Update Reason</b>    | The Marine program is changing the location where the vessel personality files (VPF) are located. |

|                         |                                                                                                   |
|-------------------------|---------------------------------------------------------------------------------------------------|
| <b>Date</b>             | 25-Oct-2019                                                                                       |
| <b>Section</b>          | Section TT - Troubleshooting Symptoms (New Format)                                                |
| <b>Procedure Number</b> | 513-t02-7413<br>(/qs3/pubsys2/xml/en/procedures/513/513-t02-7413.html)                            |
| <b>Procedure Title</b>  | C.I.B. ED-4 Preferred Source Address Conflict with OtherDevice on Network                         |
| <b>Update Reason</b>    | The Marine program is changing the location where the vessel personality files (VPF) are located. |

|                         |                                                                                                   |
|-------------------------|---------------------------------------------------------------------------------------------------|
| <b>Date</b>             | 25-Oct-2019                                                                                       |
| <b>Section</b>          | Section TT - Troubleshooting Symptoms (New Format)                                                |
| <b>Procedure Number</b> | 513-t02-7414<br>(/qs3/pubsys2/xml/en/procedures/513/513-t02-7414.html)                            |
| <b>Procedure Title</b>  | ED-4 Source Address Conflict on Network                                                           |
| <b>Update Reason</b>    | The Marine program is changing the location where the vessel personality files (VPF) are located. |

|                         |                                                                                                   |
|-------------------------|---------------------------------------------------------------------------------------------------|
| <b>Date</b>             | 25-Oct-2019                                                                                       |
| <b>Section</b>          | Section TT - Troubleshooting Symptoms (New Format)                                                |
| <b>Procedure Number</b> | 513-t02-7415<br>(/qs3/pubsys2/xml/en/procedures/513/513-t02-7415.html)                            |
| <b>Procedure Title</b>  | ED-4 Source Address Conflict on Network                                                           |
| <b>Update Reason</b>    | The Marine program is changing the location where the vessel personality files (VPF) are located. |
| <b>Date</b>             | 25-Oct-2019                                                                                       |
| <b>Section</b>          | Section TT - Troubleshooting Symptoms (New Format)                                                |
| <b>Procedure Number</b> | 513-t02-7416<br>(/qs3/pubsys2/xml/en/procedures/513/513-t02-7416.html)                            |
| <b>Procedure Title</b>  | Traffic on CAN1 Higher Than Expected                                                              |
| <b>Update Reason</b>    | The Marine program is changing the location where the vessel personality files (VPF) are located. |
| <b>Date</b>             | 25-Oct-2019                                                                                       |
| <b>Section</b>          | Section TT - Troubleshooting Symptoms (New Format)                                                |
| <b>Procedure Number</b> | 513-t02-7417<br>(/qs3/pubsys2/xml/en/procedures/513/513-t02-7417.html)                            |
| <b>Procedure Title</b>  | Traffic on CAN2 Higher Than Expected                                                              |
| <b>Update Reason</b>    | The Marine program is changing the location where the vessel personality files (VPF) are located. |
| <b>Date</b>             | 22-Jun-2020                                                                                       |
| <b>Section</b>          | Section TA - Troubleshooting Alarm Codes                                                          |
| <b>Procedure Number</b> | 513-t02-1031<br>(/qs3/pubsys2/xml/en/procedures/513/513-t02-1031.html)                            |
| <b>Procedure Title</b>  | OEM Installed Vessel Sensor Information Missing or Intermittent on Display                        |
| <b>Update Reason</b>    | Added symptom tree to manual.                                                                     |

|                         |                                                                                                                                        |
|-------------------------|----------------------------------------------------------------------------------------------------------------------------------------|
| <b>Date</b>             | 22-Jun-2020                                                                                                                            |
| <b>Section</b>          | Section TA - Troubleshooting Alarm Codes                                                                                               |
| <b>Procedure Number</b> | 513-t02-11543<br>(/qs3/pubsys2/xml/en/procedures/513/513-t02-11543.html)                                                               |
| <b>Procedure Title</b>  | OEM Installed Sensor – Shorted to Low                                                                                                  |
| <b>Update Reason</b>    | Added symptom tree to manual.                                                                                                          |
| <b>Date</b>             | 25-Jun-2020                                                                                                                            |
| <b>Section</b>          | Section TA - Troubleshooting Alarm Codes                                                                                               |
| <b>Procedure Number</b> | 513-t02-11542<br>(/qs3/pubsys2/xml/en/procedures/513/513-t02-11542.html)                                                               |
| <b>Procedure Title</b>  | OEM Installed Sensor – Shorted to High                                                                                                 |
| <b>Update Reason</b>    | Added symptom tree to manual.                                                                                                          |
| <b>Date</b>             | 05-Aug-2020                                                                                                                            |
| <b>Section</b>          | Section TA - Troubleshooting Alarm Codes                                                                                               |
| <b>Procedure Number</b> | 513-t02-11546<br>(/qs3/pubsys2/xml/en/procedures/513/513-t02-11546.html)                                                               |
| <b>Procedure Title</b>  | OEM Installed Sensor - Condition Exists                                                                                                |
| <b>Update Reason</b>    | Added symptom tree to manual.                                                                                                          |
| <b>Date</b>             | 10-Apr-2023                                                                                                                            |
| <b>Section</b>          | Section 15 - Instruments and Controls - Group 15                                                                                       |
| <b>Procedure Number</b> | 513-015-108<br>(/qs3/pubsys2/xml/en/procedures/513/513-015-108.html)                                                                   |
| <b>Procedure Title</b>  | Display Configuration                                                                                                                  |
| <b>Update Reason</b>    | Information added to procedure regarding a new feature that was implemented to read Engine Serial Number (ESN) using the ED-4 display. |

|                         |                                                                      |
|-------------------------|----------------------------------------------------------------------|
| <b>Date</b>             | 10-Apr-2025                                                          |
| <b>Section</b>          | Section L - Service Literature                                       |
| <b>Procedure Number</b> | 513-205-001<br>(/qs3/pubsys2/xml/en/procedures/513/513-205-001.html) |
| <b>Procedure Title</b>  | Additional Service Literature                                        |
| <b>Update Reason</b>    | Added PS108 to information.                                          |
| <b>Date</b>             | 17-Apr-2025                                                          |
| <b>Section</b>          | Section 1 - Operating Instructions                                   |
| <b>Procedure Number</b> | 513-101-137<br>(/qs3/pubsys2/xml/en/procedures/513/513-101-137.html) |
| <b>Procedure Title</b>  | System Indicator Lamps                                               |
| <b>Update Reason</b>    | Added references to ED-5/ED-7 and PS108 to procedure.                |
| <b>Date</b>             | 21-Apr-2025                                                          |
| <b>Section</b>          | Section 15 - Instruments and Controls - Group 15                     |
| <b>Procedure Number</b> | 513-015-047<br>(/qs3/pubsys2/xml/en/procedures/513/513-015-047.html) |
| <b>Procedure Title</b>  | Final Verification                                                   |
| <b>Update Reason</b>    | Added information related to ED-5/ED-7 into procedure.               |
| <b>Date</b>             | 21-Apr-2025                                                          |
| <b>Section</b>          | Section E - Product and System Identification                        |
| <b>Procedure Number</b> | 513-344-003<br>(/qs3/pubsys2/xml/en/procedures/513/513-344-003.html) |
| <b>Procedure Title</b>  | Cummins® Product Technology                                          |
| <b>Update Reason</b>    | Added PS108 reference to procedure.                                  |

|                         |                                                                      |
|-------------------------|----------------------------------------------------------------------|
| <b>Date</b>             | 10-Jun-2025                                                          |
| <b>Section</b>          | Section 15 - Instruments and Controls - Group 15                     |
| <b>Procedure Number</b> | 513-015-185<br>(/qs3/pubsys2/xml/en/procedures/513/513-015-185.html) |
| <b>Procedure Title</b>  | Remote Keypad                                                        |
| <b>Update Reason</b>    | Added procedure to manual.                                           |

---

**Last Modified: 11-Jul-2025**

---