



Technical Service Bulletin

Technical Service Bulletin: tsb070007

Released Date: 17-Jan-2020

Troubleshooting and Repair Direction for High Blowby and/or Oil Consumption

Troubleshooting and Repair Direction for High Blowby and/or Oil Consumption

Core Issue

See Service Bulletin, High Blowby and Lubricating Oil Consumption Caused by Dirt and Dust Ingestion, Bulletin 5613318 (</qs3/pubsys2/xml/en/bulletin/5613318.html>).

Confirmation

Resolution

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Document History

Date	Details
2012-8-20	Add components to list of requirements and improve text for clarity of document.
2020-1-17	Removed content and added direction to reference Service Bulletin 5613318.

Last Modified: 17-Jan-2020