



Technical Service Bulletin

Technical Service Bulletin: tsb070027	Released Date: 25-Jul-2007
Three-Piece Exhaust Manifolds - Unnecessary Repair	

Three-Piece Exhaust Manifolds - Unnecessary Repair

Core Issue

The purpose of this Early Field Notification is to inform the field **not** to attempt repair of K19 and QSK19 three-piece exhaust manifolds that exhibit normal traces of carbon or carbon tracking near the slip joints.

Confirmation

- QSK19 engines
- K19 engines

No engine performance concerns. Carbon tracking could possibly be present near the slip joints of the three-piece manifold.

None.

This is a normal characteristic for a three-piece manifold during the first 100 hours of operation. The carbon **must** form around the small clearances in the joints of the manifold in order for the joint to seal.

None.

Resolution

None. If the **only** symptom is carbon tracking, no repair action is necessary.

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Last Modified: 25-Jul-2007
