



Technical Service Bulletin

Technical Service Bulletin: tsb100816

Released Date: 13-Apr-2009

New Rocker Lever Cover Assembly

New Rocker Lever Cover Assembly

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

This Technical Service Bulletin supersedes SPT 07T3-3.

The new rocker lever cover assembly, Part Number 3104387, includes the cover gasket, Part Number 3104392, and the rocker lever cover isolators, Part Number 3104388. The new rocker lever cover assembly, Part Number 3104387, supersedes the old rocker lever cover, Part Number 4059375.

Warranty repairs that require the replacement of the old rocker lever cover, Part Number 4059375, can be replaced with the new rocker lever cover assembly, Part Number 3104387, **only** after **all** the old rocker lever cover field stock is depleted at the repair location.

The three tables indicate the new parts released to service, replacement parts, and compatibility of the parts.

Table 1, New Parts Being Released to Service

Part Description	Part Number		
Rocker lever cover assembly	3104387	Rocker lever cover, cover gasket, and isolators	
Cover gasket	3104392		
Isolators assembly	3104388		

Table 2, Replacement Table

Part Description	Old Part Number	New Part Number	
Rocker lever cover assembly	4059375	3104387	

Table 3, Compatibility Table			
Rocker Lever Cover Part Number	Cover Gasket Part Number	Isolator Part Number	
3104391	3104392	3104388	
4059375	4026507	3100895	
4026509	4026507	4026511	

Last Modified: 13-Apr-2009
