



Technical Service Bulletin

Technical Service Bulletin: tsb100820

Released Date: 30-Apr-2009

New Rocker Lever Housings

New Rocker Lever Housings

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

This Technical Service Bulletin announces a product improvement for the ISM engine family rocker lever housings.

This change improves sealing between the rocker lever housing and the air intake manifold. A machined groove is now present at two locations of the rocker lever housing/air intake manifold sealing surface. The changes are a result of a project to reduce the number of external leaks at the air intake manifold. This change is an obsolete/supersede.

Note : During a repair, RTV sealant should to be applied to the rocker housing grooves, when grooves are present. The repair procedure in the service manual includes this step.

This change applies to the following part numbers:

Description	Old Part Number*	New Part Number	ESN First	Production Date
Housing, Rocker Lever	3103248	2868954	35249384	26-JAN-09
Housing, Rocker Lever	3098722	2868953	35247818	17-DEC-09
Housing, Rocker Lever	3098721	2868952	35251637	03-APR-09
Housing, Rocker Lever	3098720	2868951	35250150	13-FEB-09
* Old part numbers no longer available at MDC.				December 2008

