



Technical Service Bulletin

Technical Service Bulletin: tsb101147	Released Date: 10-May-2002
Piston Inspection Procedure	

Piston Inspection Procedure

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

This service/parts topic updates the piston inspection procedure, 001-043, in the L10, L10G, M11, ISM, and QSM11, Troubleshooting and Repair Manuals with the latest piston inspection specifications (with and without bushing).

Last Modified: 10-May-2002
