



Technical Service Bulletin

Technical Service Bulletin: tsb101247	Released Date: 10-Feb-2003
Procedures 007-007 and 007-037	

Procedures 007-007 and 007-037

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

The purpose of this Service/Parts Topic is to update Procedure 007-007, Lubricating Oil Cooler Element and Procedure 007-037, Lubricating Oil System for Signature, ISX, and QSX15 series engines.

Last Modified: 10-Feb-2003
