



Technical Service Bulletin

Technical Service Bulletin: tsb101310

Released Date: 10-Sep-2003

Revised Lubricating Oil Filter Head Adapter Torquing Sequence

Revised Lubricating Oil Filter Head Adapter Torquing Sequence

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

This service/parts topic is adding a service tool and updating procedure 007-018 (</qs3/pubsys2/xml/en/procedures/10/10-007-018.html>) for the removal and installation of the lubricating oil filter head adapter.

Related Procedures

10-007-018
(</qs3/pubsys2/xml/en/procedures/10/10-007-018.html>)

Lubricating Oil Filter Head Adapter
(</qs3/pubsys2/xml/en/procedures/10/10-007-018.html>)

Last Modified: 10-Sep-2003