



Technical Service Bulletin

Technical Service Bulletin: tsb101392

Released Date: 03-Mar-2004

Cylinder Head Gasket Oil Passage Plugs

Cylinder Head Gasket Oil Passage Plugs

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

This Service/Parts Topic updates Procedure 002-004 (/qs3/pubsys2/xml/en/procedures/10/10-002-004-tr.html) for the Signature, ISX and QSX15 Engines Troubleshooting and Repair Manual, Bulletin 3666239.

Related Procedures

10-002-004-tr
(/qs3/pubsys2/xml/en/procedures/10/10-002-004-tr.html)

Cylinder Head
(/qs3/pubsys2/xml/en/procedures/10/10-002-004-tr.html)

Last Modified: 03-Mar-2004