



Technical Service Bulletin

Technical Service Bulletin: tsb101464

Released Date: 09-Jul-2004

Revised Lubricating Oil Filter (Spin-On), Procedure 007-013

Revised Lubricating Oil Filter (Spin-On), Procedure 007-013

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

This Service/Parts Topic revises Procedure 007-013 in the Troubleshooting and Repair Manual. Two new oil filter wrenches are available.

Related Procedures

10-007-013
(/qs3/pubsys2/xml/en/procedures/10/10-007-013.html)

Lubricating Oil Filter (Spin-On)
(/qs3/pubsys2/xml/en/procedures/10/10-007-013.html)

Last Modified: 09-Jul-2004