



Technical Service Bulletin

Technical Service Bulletin: tsb101467

Released Date: 14-Jul-2004

Revision to Procedure 019-110 and Procedure 019-111

Revision to Procedure 019-110 and Procedure 019-111

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

This Service/Parts Topic updates Procedure 019-110, Fueling Actuator and Procedure 019-111, Timing Actuator to include the INSITE™ electronic service tool test procedure used to determine if an actuator has failed.

Related Procedures

72-019-110 (/qs3/pubsys2/xml/en/procedures/72/72-019-110.html)	Fueling Actuator (/qs3/pubsys2/xml/en/procedures/72/72-019-110.html)
72-019-111 (/qs3/pubsys2/xml/en/procedures/72/72-019-111.html)	Timing Actuator (/qs3/pubsys2/xml/en/procedures/72/72-019-111.html)

Last Modified: 14-Jul-2004