



Technical Service Bulletin

Technical Service Bulletin: tsb101470

Released Date: 29-Jul-2004

Lubricating Oil Filter Head Adapter, Procedure 007-018 and Lubricating Oil Pan, Procedure 007-025

Lubricating Oil Filter Head Adapter, Procedure 007-018 and Lubricating Oil Pan, Procedure 007-025

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

This Service/Parts Topic revises Procedure 007-018 and 007-025 in the Troubleshooting and Repair Manual. In Procedure 007-018, an improved filter head adapter replacer, Part Number 4918222 is available. In Procedure 007-025, the old sealant, Part Number 3823494 was replaced with a new form-in-place gasket compound sealant, Part Number 3164067. The new sealant, Part Number 3164067, was released in order to reflect changes in sealants used at the production plants.

Related Procedures

10-007-018-tr (/qs3/pubsys2/xml/en/procedures/10/10-007-018-tr.html)	Lubricating Oil Filter Head Adapter (/qs3/pubsys2/xml/en/procedures/10/10-007-018-tr.html)
10-007-025 (/qs3/pubsys2/xml/en/procedures/10/10-007-025.html)	Lubricating Oil Pan (/qs3/pubsys2/xml/en/procedures/10/10-007-025.html)

Last Modified: 29-Jul-2004