



Technical Service Bulletin

Technical Service Bulletin: tsb101483

Released Date: 09-Sep-2004

Revision to Procedure 005-045, Fuel Lift Pump

Revision to Procedure 005-045, Fuel Lift Pump

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

This Service/Parts Topic revises Procedure 005-045, Fuel Lift Pump.

Related Procedures

10-005-045
(/qs3/pubsys2/xml/en/procedures/10/10-005-045.html)

Fuel Lift Pump
(/qs3/pubsys2/xml/en/procedures/10/10-005-045.html)

Last Modified: 09-Sep-2004