



Technical Service Bulletin

Technical Service Bulletin: tsb101508

Released Date: 11-Oct-2004

Lubricating Oil Pump

Lubricating Oil Pump

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

The purpose of this Service/Parts Topic is to introduce rebuild instructions for the lubricating oil pump for Signature, ISX, and QSX15 engines.

Related Procedures

10-007-031-topic
(/qs3/pubsys2/xml/en/procedures/10/10-007-031-topic.html)

Lubricating Oil Pump
(/qs3/pubsys2/xml/en/procedures/10/10-007-031-topic.html)

Last Modified: 11-Oct-2004