



Technical Service Bulletin

Technical Service Bulletin: tsb101631

Released Date: 25-Mar-2009

New Common Main Bearing Procedure

New Common Main Bearing Procedure

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

This Service/Parts Topic releases a new common Main Bearing Procedure for the M11, ISM, ISM^e, and QSM11 engines and revises the main bearing capscrew torque values for all torque-to-yield blocks, Engine Serial Number (ESN) first 35011095.

Related Procedures

101-001-006

(/qs3/pubsys2/xml/en/procedures/101/101-001-006.html)

Bearings, Main

(/qs3/pubsys2/xml/en/procedures/101/101-001-006.html)

Last Modified: 25-Mar-2009