



Technical Service Bulletin

Technical Service Bulletin: tsb101933

Released Date: 02-Aug-2006

Revision to Lower Idler Gear Remove and Install

Revision to Lower Idler Gear Remove and Install

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

This Service Parts Topic identifies the process error for removing and installing the lower idler gear. The use of a guide stud is specified for removal and installation of the gear in Procedure 001-088 of the service manual. The gear needs to be lifted over the crankshaft tone wheel to be removed and installed. The use of a guide stud will **not** allow the gear to be removed or installed.

Related Procedures

10-001-088-tr
(/qs3/pubsys2/xml/en/procedures/10/10-001-088-tr.html)

Engine Base Timing
(/qs3/pubsys2/xml/en/procedures/10/10-001-088-tr.html)

Last Modified: 02-Aug-2006