



Technical Service Bulletin

Technical Service Bulletin: tsb101939

Released Date: 06-Sep-2006

Fuel Lift Pump, Mounting Plate Torque Revision

Fuel Lift Pump, Mounting Plate Torque Revision

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

This Service/Parts Topic provides information on the mounting plate torque revision in Procedure 005-045, Fuel Lift Pump.

Related Procedures

10-005-045
(/qs3/pubsys2/xml/en/procedures/10/10-005-045.html)

Fuel Lift Pump
(/qs3/pubsys2/xml/en/procedures/10/10-005-045.html)

Last Modified: 06-Sep-2006