



Technical Service Bulletin

Technical Service Bulletin: tsb101999

Released Date: 31-Oct-2006

Rocker Lever Cover, New Embedded Gasket

Rocker Lever Cover, New Embedded Gasket

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

This Service/Parts Topic is revising the Rocker Lever Cover, Procedure 003-011. The updates are including an additional remove and install procedure for the new rocker lever cover assembly, Part Number 3104387.

Engines built after September 7, 2006, will have a cover gasket embedded into the new rocker lever cover and will include the following items;

- Rocker lever cover
- Cover gasket
- Rocker lever cover isolators.

Related Procedures

10-003-011
(/qs3/pubsys2/xml/en/procedures/10/10-003-011.html)

Rocker Lever Cover
(/qs3/pubsys2/xml/en/procedures/10/10-003-011.html)

Last Modified: 31-Oct-2006