



Technical Service Bulletin

Technical Service Bulletin: tsb102103	Released Date: 18-Dec-2006
Revision, Shop Talk, Fault Code 2272 and All Guided Steps, Fault Code 2964	

Revision, Shop Talk, Fault Code 2272 and All Guided Steps, Fault Code 2964

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

This Service/Parts Topic revises the following in the Troubleshooting and Repair Manual, CM870 Electronic Control System Signature and ISX Engines, Bulletin 4021334:

- Fault Code 2272: The Shop Talk has been updated to warn that the fault may be caused by a broken EGR valve.
- Fault Code 2964: All guided steps have been updated.

EGR Valve Position Circuit - Voltage Below Normal or Shorted to Low Source Intake Manifold Air
Temperature High - Warning

Last Modified: 18-Dec-2006
