



Technical Service Bulletin

Technical Service Bulletin: tsb102107

Released Date: 19-Dec-2006

Revisions, Remove Step, (Bearings, Connecting Rod) Procedure and Finishing Steps, (Gear Housing, Front) Procedure

Revisions, Remove Step, (Bearings, Connecting Rod) Procedure and Finishing Steps, (Gear Housing, Front) Procedure

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

This Service/Parts Topic revises the Signature, ISX, and QSX15 Service Manual, Bulletin 3666239.

1. The connecting rod guide pin part number has been added to the Remove step of Procedure 001-005 (Bearings, Connecting Rod).
2. A reference to Procedure 019-042 (Engine Speed Sensor (ESS)) has been added to the Finishing Steps of Procedure 001-033 (Gear Housing, Front) for installing the crankshaft position sensor.

Related Procedures

10-001-005-tr (/qs3/pubsys2/xml/en/procedures/10/10-001-005-tr.html)	Bearings, Connecting Rod (/qs3/pubsys2/xml/en/procedures/10/10-001-005-tr.html)
10-001-033-tr (/qs3/pubsys2/xml/en/procedures/10/10-001-033-tr.html)	Gear Housing, Front (/qs3/pubsys2/xml/en/procedures/10/10-001-033-tr.html)

Last Modified: 19-Dec-2006