



Technical Service Bulletin

Technical Service Bulletin: tsb102159

Released Date: 22-Feb-2007

Revision, Leak Test, Lubricating Oil Cooler Procedure

Revision, Leak Test, Lubricating Oil Cooler Procedure

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

This Service/Parts Topic revises the Leak Test step of Procedure 007-003, Lubricating Oil Cooler, in the Signature, ISX, and QSX15 Service Manual, Bulletin 3666239. The leak test for the oil cooler assembly is most effective when performed in water below 7°C [44°F].

Related Procedures

10-007-003-tr
(/qs3/pubsys2/xml/en/procedures/10/10-007-003-tr.html)

Lubricating Oil Cooler
(/qs3/pubsys2/xml/en/procedures/10/10-007-003-tr.html)

Last Modified: 22-Feb-2007