



Technical Service Bulletin

Technical Service Bulletin: tsb102381	Released Date: 23-Jul-2007
Revision, Shop Talk Section, Fault Code 187	

Revision, Shop Talk Section, Fault Code 187

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

This Service/Parts Topic revises the Shop Talk section of Fault Code 187 to add an explanation of fault code status so that proper troubleshooting is performed while the fault code is active.

Sensor Voltage Supply

Last Modified: 23-Jul-2007
