



Technical Service Bulletin

Technical Service Bulletin: tsb102402	Released Date: 10-Aug-2007
Revision, Circuit Illustration, Fault Codes 394 and 395	

Revision, Circuit Illustration, Fault Codes 394 and 395

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

This Service/Parts Topic revises the circuit illustration for Fault Codes 394 and 395 to correct ECM pin numbers.

Actuator Circuit Actuator Circuit

Last Modified: 10-Aug-2007
